MRN/HMR/DH/174

S.M.P. KOLKATA

एस॰एम॰पी॰ कोलकाता

H.M.(R)'S OFFICE

DIAMOND HARBOUR MAR. '2024

Dated 30.01.2024

ESTMATED FRESH WATER DRAFT FORECAST FOR THE MONTH OF March'2024 FOR DIAMOND HARBOUR FOR VESSELS OF 12KTS. & OVER (SUBJECT TO ALTERATION)

INWARD:				NOTES
Date	Α	В	С	
1st	7.9	8.1	8.3	Calculated for 12 kts River speed. Indward Draft to be reduced
2nd	7.8	8.0	8.2	by 0.1 mtr for every knot below 12 kts. Outward draft to be redu-
3rd	7.6	7.8	8.0	ced by 0.2 mtr for every knot below 12 knots.
4th	7.4	7.6	7.8	Source of the story fallot bolon 12 fallots.
*5th	7.2	7.4	7.6	
6th	7.2	7.4	7.6	2. LOA Category :
7th	7.4	7.6	7.8	A) Above 180 mtrs to 200 mtrs
8th	7.7	7.9	8.1	B) 160 mtrs to 180 mtrs.
9th	8.0	8.2	8.4	C) Below 160 mtrs.
10th	8.3	8.5	8.7	Sy Bolem 100 mag.
11th	8.4	8.6	8.8	3.a) Maximum size of vessel up to LOA 200 mtrs.
12th	8.4	8.6	8.8	b) Maximum permissible draft up to 9.5 mtrs.
13th	8.4	8.6	8.8	
14th	8.2	8.4	8.6	4. As there is no anchorage between Sagar and Diamond Harbour/
15th	8.0	8.2	8.4	Kulpi, all vessels to ensure that their engines and steering etc. are
16th	7.7	7.9	8.1	in good working order.
17th	7.5	7.7	7.9	1
18th	7.3	7.5	7.7	
*19th	7.0	7.2	7.4	5. All vessels are required to have two serviceable bower anchors.
20th	7.2	7.4	7.6	In view of strong tides at anchorage, Masters to ensure that the
21st	7.4	7.6	7.8	anchor chains, windlass etc. are in good working order.
22nd	7.6	7.8	8.0	good Horning Ordon
23rd	7.8	8.0	8.2	6. A.I.S. Pilot plug of all vessels are required to be oprational.
24th	7.9	8.1	8.3	o. 7 mot plag of all voccole are required to be optational.
25th	8.1	8.3	8.5	7. Based on Bedford - 6.2mtrs. & L.Maragolia -5.3 mtrs. LSTX-6.0
26th	8.1	8.3	8.5	The based on bouldra of this of the officers
27th	8.2	8.4	8.6	8. Maximum of three vessels may be accommodated at ancho-
28th	8.2	8.4	8.6	rage subject to tidal/weather conditions. In strong tides/adverse
29th	8.1	8.3	8.5	weather or for any other reason, number of vessels at anchorage
30th	8.0	8.2	8.4	may be reduced.
31th	7.9	8.1	8.3	inay be reduced.
3101	7.5	0.1	0.5	0. Forecast subject to alterations
OUTIA/A D				Forecast subject to alterations.
OUTWAR			7.0	
1st	7.4	7.6	7.8	1. O D'I (A/TO O) ('
2nd	7.4	7.6	7.8	from Sagar Pilot/VTS Station.
3rd	7.3	7.5	7.7	144 Insurand vessels should nonewhith six ETA Conditioned to Dilet
4th	7.3	7.5	7.7	11. Inward vesels should report their ETA Sandheads to Pilot
5th	7.2	7.4	7.6	Station and ask for pilotage instructions between ECLV (21*04'N,
6th	7.3	7.5	7.7	88*11'12"E) and Gasper Channel before proceeding up.
7th	7.4	7.6	7.8	42. Assistance is excilable from V/TMC Ctation at Holdis/Consu
*8th	7.1	7.3	7.5	12. Assistance is available from VTMS Station at Haldia/Sagar
9th	7.3	7.5	7.7	on VHF Channel 16/68 above Lower Gasper Light Vessel.
10th	7.5	7.7	7.9	12 Inward Vessels anchoring at Candhaada ta line a da ta line a
11th	7.6	7.8	8.0	13. Inward Vessels anchoring at Sandheads to keep clear the
12th	7.6	7.8	8.0	shipping lane.
13th	7.6	7.8	8.0	144 Mantanta abankusith Caman VTC far annual annual in the annual
14th	7.6	7.8	8.0	14. Master to check with Sagar VTS for any changes in the approach
15th	7.5	7.7	7.9	channel / way points to the Pilot Boarding Ground (PBG) before
16th	7.4	7.6	7.8	entering the channel.
17th	7.3	7.5	7.7	AF Draway analogy watch 9 MIF watch an Object of AC to be
18th	7.2	7.4	7.6	15. Proper anchor watch & VHF watch on Channel 16 to be
19th	7.1	7.3	7.5	maintained and M/E to be kept on short notice at the anchorage.
20th	7.2	7.4	7.6	
21st	7.3	7.5	7.7	
*22nd	7.1	7.3	7.5	
23rd	7.3	7.5	7.7	C-41
24th	7.4	7.6	7.8	Sd/-
25th	7.4	7.6	7.8	(D Sengupta)
26th	7.5	7.7	7.9	HARBOUR MASTER(RIVER)
27th	7.5	7.7	7.9	बदरगाह मास्टर (नदा)
28th	7.6	7.8	8.0	
29th	7.5	7.7	7.9	
30th	7.5	7.7	7.9	
31th	7.5	7.7	7.9	