

## कोलकाता पत्तन न्यास KOLKATA PORT\_TRUST हल्दिया गोदी परिसर HALDIA DOCK COMPLEX शिपिंग एंड कार्गी हैंडलिंग प्रभाग Shipping & Cargo Handling Division



General Cargo Berth Office, Dist. Purba Medinipur, Haldia, PIN - 721 602

July 8, 2019

हलदियाँ, पिन कोंड -721 604

No. GCB/TO/S/3/333

## CIRCULAR

It has been observed that a substantial part of the drainage system inside dock is being chocked by dry bulk cargo flown with rainwater from various storage yards. Such chocking of the drainage system eventually results in waterlogging of the open storage spaces thus creating hindrance in yard operation in general and stacking/reclaiming of cargo in particular.

In view of the above, licensees of the plots allotted inside dock for transit storage of cargo are hereby advised to take following preventive measures to stop seepage of cargo into the drains from the plots under their occupation.

- Making temporary barriers filled with cargo/ sand along the edge of the cargo stacks.
- 2. Covering of cargo stacks and securing the same with suitable tie-down arrangements during rain.

The above is for strict compliance please.

(S. Banerjee)

Dy. Manager (Sh & CH) General Cargo Berth, HDC Kolkata Port Trust

## Distribution:

- > Copy to the President, The Association of Shipping Interest in Calcutta (ASIC), 6, Netaji Subhas Road, Kolkata- 700 001 (Fax- 033-40128989) for information please.
- Copy to all Importers/ Exporters/ C & F Agents.