S.M.P. KOLKATA

MRN/HMR/DH/168 एस॰एम॰पी॰ कोलकाता

H.M.(R)'S OFFICE

DIAMOND HARBOUR SEPT'2023

Dated 31.07.2023

ESTMATED FRESH WATER DRAFT FORECAST FOR THE MONTH OFSEPT'2023 FOR DIAMOND HARBOUR FOR VESSELS OF 12KTS. & OVER (SUBJECT TO ALTERATION)

	DIAMOND	HARBOUR F	OK VESSEL	S OF 12KTS. & OVER (SUBJECT TO ALTERATION)
INWARD:				NOTES
Date	Α	В	С	
1st	9.0	9.2	9.4	Calculated for 12 kts River speed. Indward Draft to be reduced
2nd	8.9	9.1	9.3	by 0.1 mtr for every knot below 12 kts. Outward draft to be redu-
3rd	8.7	8.9	9.1	ced by 0.2 mtr for every knot below 12 knots.
4th	8.5	8.7	8.9	
5th	8.2	8.4	8.6	
6th	8.0	8.2	8.4	2. LOA Category :
7th	7.7	7.9	8.1	A) Above 180 mtrs to 200 mtrs
8th	7.5	7.7	7.9	B) 160 mtrs to 180 mtrs.
*9th	7.7	7.9	8.1	C) Below 160 mtrs.
10th	7.9	8.1	8.3	
11th	8.1	8.3	8.5	3.a) Maximum size of vessel up to LOA 200 mtrs.
12th	8.3	8.5	8.7	b) Maximum permissible draft up to 9.5 mtrs.
13th	8.4	8.6	8.8	, , , , , , , , , , , , , , , , , , , ,
14th	8.5	8.7	8.9	4. As there is no anchorage between Sagar and Diamond Harbour/
15th	8.5	8.7	8.9	Kulpi, all vessels to ensure that their engines and steering etc. are
16th	8.6	8.8	9.0	in good working order.
17th	8.5	8.7	8.9	l
18th	8.5	8.7	8.9	
19th	8.4	8.6	8.8	5. All vessels are required to have two serviceable bower anchors.
20th	8.3	8.5	8.7	In view of strong tides at anchorage, Masters to ensure that the
20tii	8.1	8.3	8.5	anchor chains, windlass etc. are in good working order.
				failchor chains, whichass etc. are in good working order.
22nd	7.9	8.1	8.3	6 A LS. Dilat plug of all vaccals are required to be enretional
23rd *24th	7.7	7.9	8.1	6. A.I.S. Pilot plug of all vessels are required to be oprational.
*24th	7.8	8.0	8.2	7 Pagad on Radford 6 Omtro 9 I Maragalia 5 0 mtro
25th	8.0	8.2	8.4	7. Based on Bedford - 6.0mtrs. & L.Maragolia - 5.2 mtrs.
26th	8.3	8.5	8.7	O Marinerum of themse was also many be a second of the distance of
27th	8.6	8.8	9.0	8. Maximum of three vessels may be accommodated at ancho-
28th	8.8	9.0	9.2	rage subject to tidal/weather conditions. In strong tides/adverse
29th	8.9	9.1	9.3	weather or for any other reason, number of vessels at anchorage
30th	8.9	9.1	9.3	may be reduced.
CUTWARR				Forecast subject to alterations.
OUTWAR				
1st	8.1	8.3	8.5	10. Pilot embarkation at Middleton Channel. Time to be confirmed
2nd	8.0	8.2	8.4	from Sagar Pilot/VTS Station.
3rd	7.9	8.1	8.3	
4th	7.8	8.0	8.2	11. Inward vesels should report their ETA Sandheads to Pilot
5th	7.7	7.9	8.1	Station and ask for pilotage instructions between ECLV (21*04'N,
6th	7.6	7.8	8.0	88*11'12"E) and Gasper Channel before proceeding up.
7th	7.4	7.6	7.8	
8th	7.3	7.5	7.7	12. Assistance is available from VTMS Station at Haldia/Sagar
9th	7.3	7.5	7.7	on VHF Channel 16/68 above Lower Gasper Light Vessel.
10th	7.4	7.6	7.8	'
11th	7.5	7.7	7.9	13. Inward Vessels anchoring at Sandheads to keep clear the
12th	7.6	7.8	8.0	shipping lane.
*13th	7.8	8.0	8.2	Frg
14th	7.8	8.0	8.2	14. Master to check with Sagar VTS for any changes in the approach
15th	7.8	8.0	8.2	channel / way points to the Pilot Boarding Ground (PBG) before
16th	7.8	8.0	8.2	entering the channel.
17th	7.8	8.0	8.2	
17th	7.7	7.9	8.1	15. Proper anchor watch & VHF watch on Channel 16 to be
				·
19th	7.7	7.9	8.1	maintained and M/E to be kept on short notice at the anchorage.
20th	7.7	7.9	8.1	
21st	7.6	7.8	8.0	
22nd	7.5	7.7	7.9	
23rd	7.4	7.6	7.8	Cal
24th	7.3	7.5	7.7	Sd/-
25th	7.4	7.6	7.8	(D Sengupta)
26th	7.6	7.8	8.0	HARBOUR MASTER(RIVER)
27th	7.8	8.0	8.2	बदरगाह मास्टर (नदा)
*28th	7.9	8.1	8.3	
29th	8.0	8.2	8.4	
30th	8.0	8.2	8.4	