MRN/HMR/	/DH/122		को	KOLKATA PORT TRUSTलकाता पत्तन न्यासH.M.(R)'S OFFICEND HARBOUR NOVEMBER'2019Dated : 24.09.2019
			H WATER	DRAFT FORECAST FOR THE MONTH OF NOV'2019 FOR ESSELS OF 12KTS. & OVER (SUBJECT TO ALTERATION)
INWARD:				NOTES
Date	Α	В	С	
1st	7.9	8.1	8.3	1. Calculated for 12 kts River speed. Indward Draft to be reduced
2nd	7.7	7.9	8.1	by 0.1 mtr for every knot below 12 kts. Outward draft to be redu-
3rd	7.5	7.7	7.9	ced by 0.2 mtr for every knot below 12 knots.
4th	7.3	7.5	7.7	
5th	7.3	7.5	7.7	
*6th	7.5	7.7	7.9	2. LOA Category :
7th	7.6	7.8	8.0	A) Above 180 mtrs to 200 mtrs
8th	7.8	8.0	8.2	B) 160 mtrs to 180 mtrs.
9th	7.9	8.1	8.3	C) Below 160 mtrs.
10th	8.0	8.2	8.4	
11th	8.0	8.2	8.4	3.a) Maximum size of vessel up to LOA 200 mtrs.
12th	8.1	8.3	8.5	b) Maximum permissible draft up to 9.5 mtrs.
13th	8.1	8.3	8.5	
14th	8.1	8.3	8.5	4. As there is no anchorage between Sagar and Diamond Harbour/
15th	8.0	8.2	8.4	Kulpi, all vessels to ensure that their engines and steering etc. are
16th	7.9	8.1	8.3	in good working order.
17th	7.8	8.0	8.2	
18th	7.7	7.9	8.1	
19th	7.6	7.8	8.0	5. All vessels are required to have two serviceable bower anchors.
20th	7.5	7.7	7.9	In view of strong tides at anchorage, Masters to ensure that the
*21st	7.8	8.0	8.2	anchor chains, windlass etc. are in good working order.
22nd	7.8	8.0	8.2	
23rd	8.0	8.2	8.4	6. A.I.S. Pilot plug of all vessels are required to be oprational.
24th	8.1	8.3	8.5	
25th	8.1	8.3	8.5	7. Based on L.Silver Tree - 4.9mtrs.(NEW) & L.Maragolia - 5.0 mtrs.
26th	8.1	8.3	8.5	
27th	8.1	8.3	8.5	8. Maximum of three vessels may be accommodated at ancho-
28th	8.0	8.2	8.4	rage subject to tidal/weather conditions. In strong tides/adverse
29th	7.9	8.1	8.3	weather or for any other reason, number of vessels at anchorage
30th	7.8	8.0	8.2	may be reduced.
OUTWAI		7.0	7.0	9. Forecast subject to alterations.
1st	7.4	7.6	7.8	40. Dilat and advetion at Middleton Observal. Time to be confirmed
2nd	7.3	7.5	7.7	10. Pilot embarkation at Middleton Channel. Time to be confirmed
3rd	7.2	7.4	7.6	from Sagar Pilot/VTS Station.
4th	7.2	7.4	7.6	44 Januard manufacture at their FTA Coundbacks to Dilat
5th	7.1	7.3	7.5	11. Inward vesels should report their ETA Sandheads to Pilot
6th	7.2	7.4	7.6	Station and ask for pilotage instructions between ECLV (21*04'N,
7th	7.2	7.4	7.6	88*11'12"E) and Gasper Channel before proceeding up.
8th	7.4	7.6	7.8	12 Appintence in queileble from VTMC Clation at Usual's (Opman
*9th	7.3	7.5	7.7	12. Assistance is available from VTMS Station at Haldia/Sagar
10th	7.4	7.6	7.8	on VHF Channel 16/68 above Lower Gasper Light Vessel.
11th	7.4	7.6	7.8	12 Inward Vacable anchoring at Conduced to keep start to
12th	7.4	7.6	7.8	13. Inward Vessels anchoring at Sandheads to keep clear the
13th	7.4	7.6	7.8	shipping lane.
14th 15th	7.4	7.6	7.8	14 Masters to produce Diver Hugli Estuary Chart through their
15th 16th	7.3	7.5	7.7	14. Masters to procure River Hugli Estuary Chart through their
16th	7.3	7.5	7.7	Agents from Chief Hydrographer, KoPT.
17th	7.3	7.5	7.7	15 Proper analysis watch & VUE watch on Channel 40 to be
18th	7.3	7.5	7.7	15. Proper anchor watch & VHF watch on Channel 16 to be
19th	7.2	7.4	7.6	maintained and M/E to be kept on short notice at the anchorage.
20th	7.2	7.4	7.6 7.7	
21st	7.3	7.5		
22nd *23rd	7.4	7.6	7.8	
23rd 24th	7.4 7.4	7.6 7.6	7.8 7.8	
25th	7.4	7.6	7.8	
26th	7.4	7.6	7.8	
27th	7.4	7.6	7.8	
28th	7.4	7.6	7.8	बंदरगाह मास्टर (नदी)
29th	7.3	7.5	7.7	
30th	7.3	7.5	7.7	
				4