

SYAMA PRASAD MOOKERJEE PORT, KOLKATA

KOLKATA DOCK SYSTEM

NIT No. SMP/KDS/Mech/SP-III/ADV/568 dated 18.01.2021.

Rate Contract for Repair of 9 nos. Ram Cylinder Assembly of KP Lock Gate operating Machinery for a period of 5 years.

ADDENDUM-I

Clarification/comment/amendment/addition/deletion/correction

Note:

1. The ADDENDUM –I should be read in conjunction with the Bidding Document (including Notice Inviting Tender).
2. Consequential changes, arising out of this ADDENDUM-I, shall be deemed to have been effected, even if the same were not incorporated specifically in the Bidding Document.
3. All other terms and conditions of the Bidding Document (including Notice Inviting Tender) shall remain unchanged.

ADDENDUM-I

Sub: Rate Contract for Repair of 9 nos. Ram Cylinder Assembly of KP Lock Gate operating Machinery for a period of 5 years.

NIT No. SMP/KDS/Mech/SP-III/ADV/568 dated 18.01.2021.

Sl. No	Clause No./ANNEXES	As specified in the Tender Document	Clarification/comment/amendment/addition/deletion/correction/ of SMP, Kolkata
1.	Clause No.10 under Special Conditions of Contract:	Inspection and testing is to be carried out by IRS System and Solution Pvt. Ltd. in presence of SMP's representative. Cost towards engagement of Inspector from IRS System and Solution Pvt. Ltd. will be borne by the contractor and the necessary arrangement for inspection at contractor's workshop/SMP site to be made by the contractor at his own cost.	<u>Addition:</u> However, necessary commutation in this connection would be made to IRS upon receipt of confirmation for inspection from the contractor.
2.	Clause No.11 under Special Conditions of Contract:	The contract period is for 5 years. For estimate and evaluation purpose, it is considered that 2 nos. Ram Cylinder Assembly at maximum and a minimum of 1 no. Ram Cylinder Assembly would be repaired under rate contract in each year of rate contract. There are 9 nos. Ram Cylinder Assembly available for repair and out of the 9 nos. Ram Cylinder Assembly, 7 nos. would required to be modified. The quantity mentioned in BOQ is for the purpose of evaluation only. However, payment would be made at actual.	<u>Clarification:</u> There are 9 nos. Ram Cylinder Assembly available for repair and out of the 9 nos. Ram Cylinder Assembly, 7 nos. are required to be modified. Minimum 1 no. Ram Cylinder Assembly per year would be repaired during the pendency of the contract period of 5 years.
3.	ANNEXE-G - Format for submitting details of Similar Work.	To be certified by Chartered Accountant.	<u>Amendment:</u> The format need not be certified by Chartered Accountant.
4.	Bid Securing Declaration Form at ANNEXE-I.		<u>Correction:</u> The words“two years”in Para-2 shall be read as“three years”.....
5.	References of drawings drawn in the Tender Document.		<u>Correction:</u> The Drawing No. E&D 109554AB wherever mentioned in the Tender Document, shall be read as Drawing No. 109554E while the Drawing No. E & D OE3742 wherever mentioned in the Tender Document, shall be read as Drawing No. OE3742.

6.	<p>1st sentence of Terms of Payment at Clause No.1 under Special Conditions of Contract:</p> <p>For each occasion of Repair of Ram Cylinder Assembly as per the item(s) mentioned in the Scope of Work, separate Work Order will be issued.</p>		<p><u>Amendment:</u></p> <p>For each occasion of repair of Ram Cylinder Assembly as per the item(s) mentioned in the Scope of Work, separate Work Order will be issued mentioning therein the details of work to be carried out.</p>
----	--	--	--